QUARTERLY STORMWATER SAMPLING ALASKAN COPPER WORKS, SEATTLE, WASHINGTON

Quarter: QI Date: 1/8/14 Sampling Locations: CB331707 and CB330001			
STORMWATER SAMPLING. According to the Industrial St regulated to collect a sample within the first 12 hours of stormwater the first storm event of that guarder.			
			ACCOUNTS AND A STATE OF THE STATE OF
storm event. Permittees need not sample outside of regular bus where there is no discharge, but must still submit a Discharge Mo	anessingurs during	ungata rom	ditione or divise a section
Time of sampling (should be within 12 hours after discharge begins):		36.	
Time of stamping (should be within 12 hours after discharge begins):			435
2. Did sampling occur within the first 12 hours of discharge?			1450
2. Did sampling occur within the first 12 hours of discharge?		Yes [No Unknown
3. If the answer to question 2 is no, explain why a sample was not collected within the first 12 hours.			
N/A			
4. For fourth quarter sampling, did the sampling occur during the first storm event of that Quarter?			
5. Sampling method (e.g., "from catch basin by hand"):	CB331707it	som cat	th basin by pole.
	CB330001:	luent p	sailer trom
6. Sampling parameters: turbidity, p.H., total copper, total zinc, total lead, total petroleum hydrocarbons (B331707: total copper, total zinc (B330001: total copper, turbid; ty, p.H.			
7. Oil Sheen Present?	<u>CB331707:</u> ☐ Yes ☑ No		
	<u>CB330001:</u> □ Y	, _	
8. Result of field measurements (pH/Turbidity):	CD221707. N.)	A.	
	CB330001: PH:	6.6 ;	runbidity: 17.58
9. Field meters calibrated to meter calibration standards prior to	sampling?		Yes No N/A
10. Comments (i.e., unusual circumstances): (B331707: no unusual circumstances			
CB330001: large puddle over CB. pulled black tabvic filter and grated cap for effluent pipe and puddle drained slowly took approx 15-20 min for puddle to drain.			
and grated carp for effluent pipe and puddle drained slowly			
took approx 15-20 min for puddle to drain.			
Name of sampler:			
Veseman minner			
Signature of sampler:		Date: _	1/8/14
VISUAL MONITORING HEMINDER (If monthly visual monitori visual monitoring on the separate required Monthly inspection form	ng has not already bo	een conduc	ted, recordathe results of
	water the same was the same and the same same and the same same and the same same same same same same same sam	ALCOHOLD STREET	Control of the Contro